

Remove 250PF from dead coil pin