

Owing to the acute shortage in materials and parts it has been found necessary to use substitute components in the various post-war models of His Master's Voice Radios. This has, in some cases, necessitated slight modifications in design, but in no case has any modification been permitted to impair the efficiency or quality of the finished machine.

Some of the components affected are valves, ganged and fixed condensers, trimmers, padders and wave change switches.

Likely substitutes for valves.

6K8-GT-----	ECH35
6K7-GT-----	EF39, 6U7G
6Q7-GT-----	EBC33, 6SQ7
6V6-GT-----	EL33
6X5-GT-----	5Y3G

:

x

: Slight alteration in wiring necessary.

x Bias voltage decreased.

x Separate filament winding on power transformer required.