

R.N.Z.

RADIO CORPORATION OF NEW ZEALAND LTD

88 COURTENAY PLACE, WELLINGTON, C.B., NEW ZEALAND.

S40/3

SERVICE SUPPLEMENT.

Subject

Date 28th May 1940


MODEL 052

5 Valve Dual Wave Receiver

note if X65 tube is not available for a replacement use 6J8g but not a 6K8g. insert 90Ω 1/3W resistor between osc. plate and coil.

(see Service Supplement S41/3 of 21st May 1941)

model 525



DESIGN LAB	MODEL 052	5 VALVE DUAL-WAVE RECEIVER.	AMENDMENTS	CHKD	DATE
DRAWN <i>fw</i>	D.NO. 324				
CHECKED <i>fw</i>		RADIO CORPORATION OF NEW ZEALAND LTD.			
DATE 11-4-40					

Direct model number commencing with "0" is it 0 zero, or letter O? Maybe "O" for Osram.

2
40